




Oprava poškodených základov stožiarov VN 364 BB - Snímka z GIS

Prev.úsek: 364/pu/v RZ Banoš- ÚV 5/364





list:2



VSTL 623209
St. oprava nie je potrebna

9 VSTL 623211

VSTL 623207

VSTL 623214

GPS: 48.74812, 19.13575

list:3

GPS: 48.74630, 19.13846

12

VSTL.11707666

13

VSTL.623192

