



Oprava poškodených základov stožiarov VN 384 - Snímka z GIS

Prev.úsek: 384/pu/v_Látky

384





list:1


GPS: 48.62632, 19.66115

1 VSTL.611707
B1

2 VSTL.611712
B2

VSTL.611719
3 B2





VSTL.611748

A

A

VSTL.611750

VSTL.611751

B2

GPS: 48.60138, 19.66058

VSTL.3401656


B1


7

8

9

10





VSTL.611820

A

14

15

A

VSTL.3401682

16

B1

VSTL.611840

17

VSTL.3401685

GPS: 48.57647, 19.63630

nepotrebná









